

E10 Release Notes for 1.1.8

Contains all changes since 1.1.7

2/24/2016

© 2016 Synapse Wireless® All rights reserved. Synapse products are patented or patents pending. Specifications are subject to change without notice.

114-001919-000-A000

Table of Contents

Introduction 1
Linux Kernel 1
References 1

Introduction

This document describes all changes introduced in the E10 stock firmware image version 1.1.8 since the previously officially released version 1.1.7.

Linux Kernel

- Updated to support iptables

References

E10 w/ 256-1 rev C PCB, 1.1 Firmware	114-001900-000-A001
E10 v1.1 SOURCE CONTROL DOCUMENT	114-001920-000-A003
E10 v1.1 BRIDGE RECOVERY SOFTWARE BINARIES	114-001914-000-A000
E10 v1.1 BRIDGE RECOVERY SOURCE CONTROL DOCUMENT	114-001915-000-A000